
DEFENSE HEALTH PROGRAM



Real Property Maintenance and Minor Construction DEFENDING STATESTICAL Fiscal Year 1997 Volume III

Approved for public releases Distribution Unlimited

The Defense Health Program spans the globe to support the Department of Defense's most important resource--active and retired military members and their families

DTIC QUALITY INSPECTED 3

19960417 092

DEFENSE HEALTH PROGRAM, VOLUME III REAL PROPERTY MAINTENANCE AND MINOR CONSTRUCTION FY 1997 BUDGET ESTIMATES

TABLE OF CONTENTS

Page No.

-	2	9
Real Property Maintenance Activities	Historic Building Costs	P RPM and Minor Construction (Over \$500k)
Exhibit OP-27	Exhibit OP-27H	Exhibit OP-27P

DEFENSE HEALTH PROGRAM APPROPRIATION FY 1997 BUDGET ESTIMATES REAL PROPERTY MAINTENANCE ACTIVITIES

DoD Component: DHP Appropriation: Operation & Maintenance

Date: Feb 96

FY 1995

	BMAR		577,621	11,291	566,330	558,597	992	2,967	1,000	0															577,621	577,621
Military	Personnel (\$000)		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
(0	Total		311,012	15,094	295,918	285,902	1,688	4,272	4,056	0	82,404	112,428	62,762	414	15,596	12,341	7,258	5,245	4,014	4,798	103,260	88,012	14,815	433	609,104	609,104
e Costs (\$00	Other		36,514	935	35,579	34,998	152	128	301	0	5,501	89,305	52,392	72	14,801	5,593	6,326	4,156	3,779	2,186	2,037	695	606	433	133,357	133,357
Operation & Maintenance Costs (\$000)	Contracts		247,394	12,123	235,271	227,045	1,239	3,940	3,047	0	76,891	20,241	10,357	342	795	5,416	737	818	29	1,709	88,628	81,661	6,967	0	433,154	433,154
Operation	Civilian Personnel		27,104	2,036	25,068	23,859	297	204	708	0	12	2,882	13	0	0	1,332	195	271	168	903	12,595	5,656	6,939	0	42,593	42,593
	Workload Data (1)																									
	Functional Category at Work Functions	Active Installations	1. Maintenance & Repair	a. Utilities	b. Other Real Property	(1) Buildings	(2) Other Facilities	(3) Pavements	(4) Land	(5) Railroad Trackage	2. Minor construction	3. Operation of Utilities	a. Electricity-Purchased	b. Electricity-In House	c. Heat-Purchased Steam/Water	d. Heat-In House Generated Steam/Water	e. Water Plants & Systems	f. Sewage Plants & Systems	g. Air Conditioning & Refrigeration	h. Other	4. Other Engineering Support	a. Services	b. Admin & Overhead	c. Rentals, Leases & Easements	Total Active Installations	Inactive Installations Grand Total

(1) The majority of real property maintenance support is purchased from host installation in the form of lump sum reimbursements. In many instances, medical activities co-exsist with other non-medical operations. Additionally, the quantification of workload data in terms of its utility as a management tool has not been cost effective. As a result, workload data is not included.

DEFENSE HEALTH PROGRAM APPROPRIATION FY 1997 BUDGET ESTIMATES REAL PROPERTY MAINTENANCE ACTIVITIES

DoD Component: DHP

Appropriation: Operation & Maintenance

Date: Feb 96

9	
9	
0	
_	
Ŧ	

		Operation & Maintenance Costs (\$000)	ice Costs (\$00	(0	Military	
runctional Category at Work Functions Date	Workload Civilian Data (1) Personnel	Contracts	Other	Total	(\$000)	BMAR
Active Installations						
1 Mailtonna 0 D	00,70		900	200	c	000
1. Mainenance & Kepair	21,039		44,208	301,010	0	0.28,59.5
a. Utilities	3,291		1,417	17,763	0	11,918
b. Other Real Property	18,348	221,808	43,091	283,247	0	616,675
(1) Buildings	16,638		41,841	274,200	O	606,771
(2) Other Facilities	275		613	2.340	C	1.072
(3) Pavements	447	1.137	197	1.781	0	8.832
(4) Land	988		440	4,926	0	0
(5) Railroad Trackage	0		0	0	0	0
2. Minor construction	0	46,586	8,685	55,271	0	
2 Omenand of 1141114	000 0		to	7	c	
o. Operation of Outsides	2,889		87,099	117,492	>	
a. Electricity- Purchased	10		52,211	63,962	0	
b. Electricity-In House	0	454	166	620	0	
c. Heat-Purchased Steam/Water	0	4,045	12,141	16,186	0	
d. Heat-In House Generated Steam/Water	1,496		10,034	16,418	0	
e. Water Plants & Systems	200	1,719	5,513	7,432	0	
f. Sewage Plants & Systems	260	1,736	3,478	5,474	0	
g. Air Conditioning & Refrigeration	143	2,921	1,114	4,178	0	
h. Other	780	0	2,442	3,222	0	
4. Other Engineering Support	12,137		4,375	95,338	0	
a. Services	6,174		1,828	73,097	0	
b. Admin & Overhead	5,963	13,	1,048	20,540	0	
c. Rentals, Leases & Easements	0		1,499	1,701	0	
Total Active Installations	36,665	387,779	144,667	569,111	0	628,593
Inactive Installations						
Grand Total	36,665	387,779	144,667	569,111	0	628,593

(1) The majority of real property maintenance support is purchased from host installation in the form of lump sum reimbursements. In many instances, medical activities co-exsist with other non-medical operations. Additionally, the quantification of workload data in terms of its utility as a management tool has not been cost effective. As a result, workload data is not included.



691,050 691,050

DEFENSE HEALTH PROGRAM APPROPRIATION FY 1997 BUDGET ESTIMATES REAL PROPERTY MAINTENANCE ACTIVITIES

Appropriation: Operation & Maintenance DoD Component: DHP

Date: Feb 96

FY 1997

691,050 11,729 679,321 669,724 1,066 8,531

F	Workload	Operation	Operation & Maintenance Costs (\$000)	ce Costs (\$00)	(0	Military	
Fulletional Category at Work Functions	Data (1)	Personnel	Contracts	Other	Total	(\$000)	BMAR
Active Installations							
		1		1		(0
 Maintenance & Repair 		18,097	229,430	45,215	292,742	>	050,1760
a. Utilities		2,802	11,648	1,207	15,657	0	11,729
b. Other Real Property		15,295	217,782	44,008	277,085	0	679,321
(1) Buildings		13,726	211,213	42,674	267,613	0	669,724
(2) Other Facilities		350	1,886	721	2,957	0	1,066
(3) Pavements		450	1,226	200	1,876	0	8,531
(4) Land		692	3,457	413	4,639	0	0
(5) Railroad Trackage		0	0	0	0	0	0
2. Minor construction		0	36,432	3,188	39,620	0	
3. Operation of Utilities		2,851	32,125	88,489	123,465	0	
a, Electricity- Purchased		10	16,004	52,760	68,774	0	
b. Electricity-In House		0	468	169	637	0	
c. Heat-Purchased Steam/Water		0	4,469	12,766	17,235	0	
d. Heat-In House Generated Steam/Water		1,526	4,919	10,420	16,865	0	
e. Water Plants & Systems		200	1,606	5,512	7,318	0	
		260	1,684	3,510	5,454	0	
g. Air Conditioning & Refrigeration		147	2,866	854	3,867	0	
h. Other		708	109	2,498	3,315	0	
4. Other Engineering Support		12,386	79,312	3,661	95,359	0	
a. Services		6,323	66,445	1,690	74,458	0	
b. Admin & Overhead		6,063	12,765	1,236	20,064	0	
c. Rentals, Leases & Easements		0	102	735	837	0	
Total Active Installations		33,334	377,299	140,553	551,186	0	691,050
Inactive Anstallations Grand Total		33,334	377,299	140,553	551,186	0	691,050

(1) The majority of real property maintenance support is purchased from host installation in the form of lump sum reimbursements. In many instances, medical activities co-exsist with other non-medical operations. Additionally, the quantification of workload data in terms of its utility as a management tool has not been cost effective. As a result, workload data is not included.

Exhibit OP-27 (Page 4 of 4)

DEFENSE HEALTH PROGRAM APPROPRIATION FY 1997 BUDGET ESTIMATES BACKLOG OF MAINTENANCE AND REPAIRS (BMAR) OF REAL PROPERTY (\$ IN THOUSANDS)

DoD Component: DHP Appropriation: Operation & Maintenance

Date: Feb 96

		FY 1995	FY 1996	FY 1997	
BAC	A. BACKLOG - BEGINNING OF YEAR	563,042	584,626	638,051	
(BAC)	BACKLOG CARRIED FORWARD FROM PRIOR YEARS) MINUS BACKLOG MORE THAN FOUR YEARS OLD)	550,539 (3,068)	577,621 (4,458)	628,593 (4,277)	
(ADJ	(ADJUSTED BACKLOG CARRIED FORWARD)	547,471	573,163	624,316	
(FOR	(HOREIGN CURRENCY REVALUATION)	1/5,61 0	11,463	13,/35 0	
REO	REQUIREMENTS:	344,668	353,103	364,187	
(REC	RECURRING MAINTENANCE & REPAIRS	205,377	207,349	211,932	
(MAZ) (BAZ)	(MAJOR REPAIR PROJECTS) (BACKLOG DETERIORATION)	91,462 47,829	95,016 50,738	98,609 53,646	
TOT	TOTAL REQUIREMENTS (A + B)	907,710	937,729	1,002,238	
PRO	PROGRAM ADJUSTMENTS:	330,089	309,136	311,188	
(DIR	(DIRECT PROGRAM FUNDING)	311,012	301,010	292,742	
E E	(FUNDS MIGRATION FROM OTHER PROGRAM AREAS) NET OTHER ADIUSTMENTS)	12,000	0 8.126	0 18.446	
BAC	BACKLOG - END OF YEAR (C - D)	577,621	628,593	691,050	
PERC	PERCENT BMAR CHANGE (E / A)	103%	108%	108%	



DEFENSE HEALTH PROGRAM APPROPRIATION FY 1997 BUDGET ESTIMATES OPERATIONS & MAINTENANCE COSTS Real Property Maintenance and Minor Construction Projects (HISTORIC BUILDINGS COSTS)

DoD Component: DHP Appropriation: O&M

(000\$)

HISTORIC BUILDINGS (Excluding Family Housing)	FY 1995	FY 1996	FY 1997
A. No. of Facilities	15	15	15
B. Minor Construction	511	115	155
C. Major Repair (projects costing over \$25,000.00)	406	1,405	2,333
D. Recurring Maintenance (projects costing \$25,000.00 or under)	957	642	655
Grand Total	1,874	2,162	3,143

Major Repair/Major Repair With Concurrent Minor Construction Projects (Costing more than \$500,000.00) Defense Health Program Appropriation Real Property Maintenance Activities FY 1997 Budget Estimates

FY 1995 State	Location/Installation	Project Title	(\$000) Cost
AK	Bassett Army Hospital	Fire Door Dampers, Fire Alarms	1,275
	Justification: Life, safety upgrade.	grade.	
CA	NH CPEN	Repair Hosp Elevator Phase I, Bldg H-100, R1-87(01)	1,104
	Justification: Repair by replacement of six ele problems with these elevators, such as; vibrat on and between floors, skip "punched" floors floor level. Adversely affects mission, safety.	Justification: Repair by replacement of six elevators. The hospital is experiencing numerous problems with these elevators, such as; vibrate excessively when running at rated speed; get stuck on and between floors, skip "punched" floors; and doors open up to 12 inches above or below floor level. Adversely affects mission, safety.	
CT	NH GROTN	RPR A/C, Bldg 449, RA1-89(2)	1,890
	Justification: Repair by replace cooling tower systems. Humid recovery, labor and delivery, et affects mission, safety, morale.	Justification: Repair by replacement needed to deteriorated and inefficient air conditioning and cooling tower systems. Humidity and temperature control needed to main operating rooms, recovery, labor and delivery, etc. Air conditioning is mandatory for infection control. Adversely affects mission, safety, morale.	
CO	Fitzsimons AMC	Repair Elevators #1, #2, and #3 Bldg 500	066
	Justification: Age of elevators requir to repair and maintain the equipment.	Justification: Age of elevators require constant repairs. DPW personnel do not have the expertise to repair and maintain the equipment.	

FY 1995 State	Location/Installation	Project Title	(\$000) Cost
CO	Fitzsimons AMC	Repair Elevators East and West Wings of Bldg 500	534
	Justification: Age of elevators requir to repair and maintain the equipment.	Justification: Age of elevators require constant repairs. DPW personnel do not have the expertise to repair and maintain the equipment.	
00	USAF Academy	North Central Corridor Clinic Remodel/Bldg 4102	1,021
	Justification: Comprehensiv install mandatory fire sprink ventilation systems; and inco	Justification: Comprehensive remodeling to eliminate life safety deficiencies; upgrade lighting; install mandatory fire sprinkler system, fire alarms, and fire detection systems; improve existing ventilation systems; and incorporate expanded/relocated clinics.	
DC	WRAMC	Install Fire Alarm System, Bldg. 2	1,219
	Justification: Project remov supplementary modules, fire existing radio transmitter.	Justification: Project removes existing alarm system and installs new voice evacuation system, supplementary modules, fire alarms graphics annunciator panels and integrates system into existing radio transmitter.	
币	NH JAX	Renovate Food Services Area, Bldg. H-2080, RCE4-91	2335
	Justification: Repairs requir lighting. Exhaust vents and Replacement needed for plu	Justification: Repairs required include steam distribution, floor drains, exhaust ventilation, and lighting. Exhaust vents and hoods will be replaced to include fire protection equipment. Replacement needed for plumbing in crawlspace and cooling equipment.	

FY 1995 State	Location/Installation	Project Title	(\$000) Cost
邑	MacDill AFB	Alter Food Prep Area	200
	Justification: Replacement and moderniz facility to improve work space and flow.	Justification: Replacement and modernization of existing food preparation area in the medical facility to improve work space and flow.	
GA	Martin Army Hospital	Duct Cleaning	700
	Justification: To comply with OSHA standards.	1 OSHA standards.	
GA	EAMC	Repair 12 Air Handler Units	540
	Justification: To maintain JG	Justification: To maintain JCAHO accreditation standards.	
GE	Bitburg AB	Replace Interior Doors, LS Requirement	524
	Justification: Interior doors	Justification: Interior doors to 1950's-era building require upgrade to meet life safety requirements.	
GE	Ramstein AB	Repair 4th Floor, Repair Heat Bldg 2121	2,015
	Justification: Project provide HVAC systems to meet curre	Justification: Project provides comprehensive repair to existing mechanical room and upgrades HVAC systems to meet current demands for heating/cooling.	
GU	Andersen AFB	Replace Clinic Carpet	530
	Justification: Replace existin	Justification: Replace existing worn floor coverings to improve facility's appearance.	

OP-27P Real Property Mainter

FY 1995 State	Location/Installation	Project Title	(\$000) Cost
HI	NMCL PEARL	Replace Roof, RC1-95	593
	<u>Justification</u> : Reparis replacement to numerous roof leaks during and after potentially loss of the structure itself.	Justification: Reparis replacement to deteriorated, leaking roof. This outpatient clinic suffers numerous roof leaks during and after rains. Failure to repair will impact on usage of building and potentially loss of the structure itself.	
IL	NH GLAKES	Install Dampers/Repair Fire Dampers System, Bldg. 200-H, R5-92	2,924
	Justification: This project is handling unit shutdown capa provide fire alarm and electrismoke dampers as required.	<u>Justification</u> : This project is required based on the need for fire/smoke dampers and automatic air handling unit shutdown capability as required by NFPA 101, the Life Safety Code. Project will provide fire alarm and electrical system, air handling units, fire dampers, smoke barriers, and smoke dampers as required.	
JA	NH OKI	Replace Chillers (Camp Lester), Bldg. 6010, RA1-93	539
	Justification: Repair by replac centrifugal water chillers which Maintenance and repair is mor stock and having to back-orden no longer available after 1995.	<u>Justification</u> : Repair by replacement of 37 year old chiller plant consisting of four 350-ton centrifugal water chillers which use refrigerant R-11. these chillers have exceeded their useful life. Maintenance and repair is more and more difficult and costly due to non-availability of parts in stock and having to back-order for special production. The refrigerant R-11 will be phase out and no longer available after 1995.	
JA	Yokota AB	Correct Life Safety Hospital	2,845

FY 1995 <u>State</u>	<u>Location/Installation</u>	<u>Project Title</u>	(\$000) Cost
	Justification: Provides correcticonpliance with codes.	Justification: Provides corrective actions to eliminate life safety deficiencies and bring facility into compliance with codes.	
JA	Yokota AB	Upgrade Mechanical/Electrical	1,386
	Justification: Upgrade aged sy	systems. Addition of energy efficient control systems and lighting.	
KY	Blanchfield Army Hospital	Replace Fire Alarm System	850
	Justification: Life, safety upgrade.	ade.	
KY	Blanchfield Army Hospital	Energy Remediation 3 Dental Clinics	1,982
	Justification: Energy remediat old and unreliable.	<u>Justification</u> : Energy remediation contract to upgrade heating/cooling system. Present system is old and unreliable.	
KY	Blanchfield Army Hospital	Energy Remediation TMC 2-8	772
	Justification: Energy remediat old and unreliable.	Justification: Energy remediation contract to upgrade heating/cooling system. Present system is old and unreliable.	

FY 1995 <u>State</u>	Location/Installation	Project Title	(\$000) Cost
MD	Andrews AFB	Replace Refrigerant Systems	850
	Justification: Replacement of all 1950's vintage will eliminate inefficient, uneconomical systems.	of all 1950's vintage refrigerant systems in medical center. Project sconomical systems.	
МО	Leonard Wood Army Hosp	Replace Cooling Towers	818
	Justification: Brings equipm	Justification: Brings equipment into compliance with current codes and standards.	
МО	Scott AFB	Renovate Lambert Clinic	898
	Justification: Revitalize clin 131st to share this space wit alterations to HVAC system ray unit.	Justification: Revitalize clinic space located in first floor of 131 FW HQ building to allow the 131st to share this space with a satellite clinic of the Scott Medical center. Project includes alterations to HVAC system, electrical system, plumbing, and lead lining for installation of an X-ray unit.	
NE	Offutt AFB	Alter/Repair Bldg 527	1,544

Justification: Alteration and repair of existing medical facility to include modernization of wall and floor coverings, drapes, furnishings, and artwork. Aged appearance detracts from patient

perception of quality of care.

Major Repair/Major Repair With Concurrent Minor Construction Projects Defense Health Program Appropriation Real Property Maintenance Activities (Costing more than \$500,000.00) FY 1997 Budget Estimates

FY 1995			(\$000)
State	Location/Installation	Project Title	Cost
Pan	Howard AFB	Clinic Renovation	3,273
	Justification: Upgrade the a Army Medical Facility will to meet the needs of a large	<u>Justification</u> : Upgrade the aging facility to meet expanding mission requirements. Closure of Army Medical Facility will necessitate the expansion of clinical capabilities at the Howard Clinic to meet the needs of a large beneficiary population.	
PR	NH ROOSRD	Replace Medical Gas/Vacuum System	550
	Justification: Current syste NFPA requirements. Proje operating rooms.	Justification: Current system is beyond economical repair and does not comply with JCAHO and NFPA requirements. Project will repair numerous oxygen leaks and provide adequate vacuum in operating rooms.	
RI	NH NPT	Repairs and Alterations to Medical Support Spaces, Bldg. 44, RCE1-91	1,066
	Justification: Facility constexterior brick veneer, repla	Justification: Facility constructed in 1942. Exterior repairs include repointing and sealing the exterior brick veneer, replacing the windows, and replacing the deteriorated, leaking roof.	
SC	NH BFT	Replace Liquid Chillers, RA8-93(2)	542
	Justification: Repair by rep	Justification: Repair by replacement for two 250 ton centrifugal liquid chillers which were	

chillers which was installed in 1976. Replace condencer water pumps, chill water pumps and hot

water pumps. Retrofitting was considered but the cost is exuberant.

installed in 1949. Chillers are dysfunctional and beyond repairs. Replace one 580 ton liquid

FY 1995 State	Location/Installation	Project Title	(\$000) Cost
SC	NH BFT	Replace Air Handling Units R2-94	521
	Justification: Repairs required to the rusted, some have holes in the casing deteriorated for proper heat transfer.	<u>Justification</u> : Repairs required to the existing air handling units. Air handling units casings are rusted, some have holes in the casings, filter racks are rusted and deteriorated, and fins are too deteriorated for proper heat transfer.	
SC	NH CHASN	Replace Chilled Water Plant, NH-1, RC1-95	1,470
	Justification: The current cl 15 years. Chillers are leakin provide replacement of the towers and pumps.	<u>Justification</u> : The current chillers were installed in 1973. The life expectancy of the equipment is 15 years. Chillers are leaking and numerous down times have become routine. Project will provide replacement of the current chillers with three 470 tons each centrifugal units, new cooling towers and pumps.	
TX	NH CORPUS	Repair Air Handlers and Duct Work, H-100, R2-92	1,325
	Justification: Repair by replacement all air handl andoutside air intake ducts. These repairs are ne occured from the high salinity of the ambient air.	<u>Justification:</u> Repair by replacement all air handler units, the pre-heat coils, filter racks, andoutside air intake ducts. These repairs are necessary due to major corrosion which has occured from the high salinity of the ambient air.	
TX	BAMC	Rhodes Dental Clinic Renovation	716
	Justification: To correct de and OSHA standards.	<u>Justification:</u> To correct deficiencies in the physical plant, and to meet current infection control and OSHA standards.	

FY 1995 State	Location/Installation	Project Title	(\$000) Cost
TX	Lackland AFB	Upgrade Interior Bldg 7206	700
	Justification: 1951-era building which houses lequired to match ongoing exterior upgrade. E near termination of equipment life expectancy.	Justification: 1951-era building which houses Behavioral Analysis Clinic. Interior upgrade required to match ongoing exterior upgrade. Electrical and mechanical systems substandard and near termination of equipment life expectancy.	
UK	Lakenheath AB	Repair Main Hospital	3,900
	Justification: Comprehensiv Project corrects numerous li	Justification: Comprehensive project to repair aged facility and compensate for inadequate space. Project corrects numerous life safety problems to bring facility into compliance with code.	
UK	Lakenheath AB	Hospital Water Storage	989
	Justification: Complete moc	Justification: Complete modernization of medical facility's water storage capability.	
UK	Lakenheath AB	Construct Flight Medicine Addition	841

e and Minor Construction - Projects Over \$500,000 (Page 9 OP-27P Real Property Mainter

Justification: Existing facility in disrepair. Warehouse layout inadequate for volume of materiel

Repair/Renovate Med Supply Bldg 930

requiring storage and handling. Environmental systems/controls inadequate for maintaining

correct storage climate.

Justification: Addition required to meet increased patient/staff space requirements. Existing

space inadequate.

Lakenheath AB

UK

995

FY 1995 State	Location/Installation	Project Title	(\$000) Cost
VA	NMCL QUANT	Repair Replace Med Clinic (Windows), Bldg. 2200, RA1-88(3)	585
	Justification: The existing w leak excessively allowing infimprove energy efficiency at	Justification: The existing windows are completely worn out and nonfunctional. The windows leak excessively allowing infiltration of water, outside air, and insects. New windows will improve energy efficiency and enhance the quality of the working environment.	
WA	Fairchild AFB	Interior/Utility Upgrade Bldg 9000	2,800
	Justification: Project will relincident to work. Replacemincluded. Associated with M	Justification: Project will replace and extend the existing HVAC system and remove asbestos incident to work. Replacement of medical air compressor, vacuum pump, and gas columns included. Associated with MILCON project to correct utility/life safety problems.	
WA	Fairchild AFB	Upgrade MTF Interior	825
	Justification: Overall upgrac appearance affects patient's	Justification: Overall upgrade to wall and floor coverings, and furnishings. Worn, outdated appearance affects patient's perception of quality of care.	
WA	McChord AFB	Renovate Dental Clinic	1,270

Justification: Project upgrades interior/exterior of outdated dental clinic.

Defense Health Program Appropriation FY 1997 Budget Estimates Real Property Maintenance Activities

Major Repair/Major Repair With Concurrent Minor Construction Projects (Costing more than \$500,000.00)

	Project Title
	Location/Installation
FY 1995	<u>State</u>

(\$000) Cost

102	53,163	53,265	0
Total Minor Construction:	Total Repair and Maintenance:	Total Active Installations:	Total Inactive Installations:

53,265 Grand Total:

FY 1996 <u>State</u>	Location/Installation	Project Title	(\$000) Cost
AK	Bassett Army Hospital <u>Justification</u> : Project needec	Bassett Army Hospital Repair/Upgrade Electrical System, Phase II <u>Justification</u> : Project needed to correct serious deficiencies. Project will bring a reliable system on line.	1,380
AK	Bassett Army Hospital Justification: Repairs will b	Bassett Army Hospital Replace Failed Water Lines, Valves and Drains Justification: Repairs will bring the entire plumbing system into compliance with JCAHO standards.	3,050
AZ	Luke AFB Justification: Telephone sw	Luke AFB Telephone Switch Justification: Telephone switch system required in conjunction with military construction project	200
CA	NH CPEN	Repairs to Air Conditioning System, Bldg H-100, R2-89(2)	779
	Justification: Phase II. Repenergy efficient system. Reaffecting mission, safety.	Justification: Phase II. Repair by replacement needed to HVAC system by replacing with an energy efficient system. Repairs needed frequently to deteriorating existing system. Adversely affecting mission, safety.	

FY 1996 State	Location/Installation	Project Title	(\$000) Cost
CA	NH LEMOORE	Provide Smoke Barriers and Smoke Compartments, Bldg 930, R1-90	765
	Justification: Phase II. Repair by replacement nee conditioning and cooling tower systems. Humidity operating rooms, recovery, labor and delivery, etc. control. Adversely affects mission, safety, morale.	<u>Justification</u> : Phase II. Repair by replacement needed to deteriorated and inefficient air conditioning and cooling tower systems. Humidity and temperature control needed to main operating rooms, recovery, labor and delivery, etc. Air conditioning is mandatory for infection control. Adversely affects mission, safety, morale.	
CA	Edwards AFB	Renovate Surgery/replace or HVAC	552
	Justification: Project replace ceiling, and creates a new ba standards.	<u>Justification</u> : Project replaces existing HVAC system, upgrades electrical components, replaces ceiling, and creates a new backstairs exit. Current layout does not meet modern surgical practice standards.	
CA	Travis AFB	Repair/Repaint Exterior	066
	Justification: Upkeep on ext facilities.	<u>Justification</u> : Upkeep on exterior surfaces to maintain appearances for one of AF's newer medical facilities.	
C.A	Travis AFB	Repair Hospital EMCS	1,500

Justification: Current EMCS is outdated and has limited repair parts capability.

FY 1996 <u>State</u>	Location/Installation	Project Title	(\$000) Cost
DC	WRAMC	Repair HVAC System, Bldg 54A	920
	Justification: Project correct pressurization standards and USAEPA standards.	Justification: Project corrects mechanical system deficiencies in order to meet stringent lab pressurization standards and removes asbestos. Repairs are needed to meet OSHA, ACGIH, and USAEPA standards.	
DE	Dover AFB	CID Upgrade	880
	Justification: Upgrade to in furniture, and signage. Impl	Justification: Upgrade to interior of bldg 300 to include wall coverings, drapes, pictures, furniture, and signage. Improved appearance key to positive patient view of medical facility.	
DE	Dover AFB	Replace HVAC Labor/Surgery	3,000
	Justification: Current ventil provides new HVAC, sprind deficiencies.	Justification: Current ventilation system inadequate. Return air requirement not met. Project provides new HVAC, sprinkler system, and fire detection system to correct life safety deficiencies.	
GA	EAMC	Replace Chiller	1,865

Justification: Current equipment has deteriorated beyond repair and must be replaced.

Major Repair/Major Repair With Concurrent Minor Construction Projects Defense Health Program Appropriation Real Property Maintenance Activities FY 1997 Budget Estimates

(Costing more than \$500,000.00)

FY 1996 <u>State</u>	Location/Installation	Project Title	(\$000) Cost
GA	БАМС	Renovate, Upgrade Heating System	1,200
	Justification: Modification will m with current standards and codes.	<u>Justification:</u> Modification will make system energy efficient and bring equipment into compliance with current standards and codes.	
GA	EAMC	Renovate Fire Sprinkler System	1,121
	Justification: Repairs will b	Justification: Repairs will bring the fire sprinkler system into compliance with JCAHO standards.	
GA	EAMC	Replace Electrical Power Transfer Switches	820
	Justification: These switches equipment is 20 years old.	s transfer commercial power to emergency generators and current	
GA	EAMC	Replace Pneumatic Transit Tube System	009
	Justification: Current equipment is over 25 years old.	nent is over 25 years old.	
GA	ЕАМС	Painting, Wall-Papering, and Ceiling and Floor Tile Replacement	950
	Justification: Preventive macenter.	<u>Justification</u> : Preventive maintenance is required to portray professional image of the medical center.	

FY 1996 State	Location/Installation	Project Title	(\$000) Cost
GA	EAMC	Replace Fire alarm System	820
	Justification: Replacement	system is in compliance with the ADA.	
GA	Moody AFB	Repair/Alter Dental Clinic	160
	Justification: This project will significantly addition and alteration to exiting facilities. administrative functions of the dental clinic DTRs, laboratory, and central sterilization.	Justification: This project will significantly upgrade dental services through a combination of addition and alteration to exiting facilities. It entails a 2,000 SF addition to accommodate administrative functions of the dental clinic and renovation of 3,867 SF to accommodate 13 DTRs, laboratory, and central sterilization.	
GU	NH Guam	Replace Air Conditioning and Refrigeration Equipment Bldg. 1, R2-94	1,099
	Justification: Repair by rep an environmentally conforn are using Freon 11 and 12 v they emit.	<u>Justification</u> : Repair by replacement to the existing air conditioning and refrigeration systems with an environmentally conforming type air conditioning and refrigeration system. Current systems are using Freon 11 and 12 which are considered hazardous substances due to toxic vapors that they emit.	
GU	Andersen AB	Add/Alter OB/GYN	009
	Justification: Project requir	Justification: Project required to expand/provide space for expanded obstetrical/gynecological	

services.

FY 1996 State	Location/Installation	Project Title	(\$000) Cost
HI	Schofield Barracks	Renovate Bldgs 686, 677, 681, 684, 685	8,100
	Justification: Replacement s	Justification: Replacement system is in compliance with the ADA.	
IC	NH KEFLVK	Interior Repairs and Life Safety Project, Bldg. 710, R35-93	705
	Justification: This project pr hazards. Repairs include 1) replace generator and underg	<u>Justification</u> : This project provides essential repairs to correct health, safety, and fire safety hazards. Repairs include 1) fire rated ceiling and wall, 2) heating and ventilating system, 3) replace generator and underground fuel oil tank, 4) repair refrigeration alarm system.	
IL	NH GLAKES	Replace Absorption Chiller Units, Bldg 130H, R12-93	528
	Justification: Repair by replanatural gas fired absorption or replacement. The existing syrepairs. This equipment is repairs.	Justification: Repair by replacement of two existing single-effect chiller units with new two stage natural gas fired absorption chillers. the existing units are 21 years old and are in need of replacement. the existing system has recently required increased and costly maintenance and repairs. This equipment is required to support the current mission of the hospital complex.	
11	NH GLAKES	Electrical/Structural Repairs, 200-H, RC4-90	1,233

HVAC and potable water. Also, repair by replacement deficient electric panels to meet current

codes, and cooling tower to correct safety and operational discrepancies in the 34 year old structure. Adversely affects mission, safety, morale. Minor construction cost - \$79K.

Justification: Repair by replacement all pumps, controls, gauges, and operating systems for

Defense Health Program Appropriation FY 1997 Budget Estimates Real Property Maintenance Activities

Major Repair/Major Repair With Concurrent Minor Construction Projects (Costing more than \$500,000.00)

FY 1996 State	Location/Installation	Project Title	(\$000) Cost
II.	Scott AFB	Emergency Power Companion	928
	Justification: Project upgrathe basement of the facility. power sources are lost.	Justification: Project upgrades the current system and provides an emergency power plant outside the basement of the facility. Provides the medical facility electrical power in the event commercial power sources are lost.	
JA	NH OKI	Replace HVAC System (Phase I) Bldg. 6000, R5-93(1)	3,037
	Justification: Repair by replace centrifugal water chillers which Maintenance and repair is more stock and having to back-orden no longer available after 1995.	Justification: Repair by replacement to 37 year old chiller plant consisting of four 350-ton centrifugal water chillers which use refrigerant R-11. these chillers have exceeded their useful life. Maintenance and repair is more and more difficult and costly due to non-availability of parts in stock and having to back-order for special production. The refrigerant R-11 will be phase out and no longer available after 1995.	
JA	NH OKI	Replace Boilers (Camp Lester), Bldg. 6010, R3-93	664

affects compliance of room pressurization criteria, indoor air quality, as well as the overall system resulting dampness, mildew and fungus growth, odors, accelerated corrosion and deterioration of Justification: Repair by replacement of entire (1950's vintage deteriorating heating, ventilation, performance. For cooling, high room humidities have resulted in dew point condensation with and air conditioning system (HVAC). The HVAC system is presently not air-balanced, which medical equipment.

Major Repair/Major Repair With Concurrent Minor Construction Projects (Costing more than \$500,000.00) Defense Health Program Appropriation FY 1997 Budget Estimates Real Property Maintenance Activities

FY 1996 <u>State</u>	Location/Installation	Project Title	(\$000) <u>Cost</u>
JA	Yokota AB	Correct Life Safety Clinic	3,000
	Justification: Correction of l	Justification: Correction of life safety deficiencies to bring facility into compliance with code.	
JA	Yokota AB	Extend Emergency Power	750
	Justification: Project expand	Justification: Project expands emergency power to currently unprotected areas.	
KO	121st Evacuation Hospital	Renovate Pathology Department	803
	Justification: Hospital will n	Justification: Hospital will not maintain JCAHO accreditation without this modification.	
KO	121st Evacuation Hospital	Roof Replacement Phase II	550
	Justification: Current roof ca patients.	<u>Justification</u> : Current roof causes leakage to medical equipment and interruption of service patients.	
KO	121st Evacuation Hospital	Renovate Yongsan Veterinary Clinic	751
	Justification: Upgrade will provide ac better utilize Veterinary Clinic space.	<u>Justification</u> : Upgrade will provide adequate lighting, ventilation and drainage to the kennels and better utilize Veterinary Clinic space.	

FY 1996 <u>State</u>	Location/Installation	Project Title	(\$000) Cost
ΓĄ	Bayne-Jones Army Hospital	HVAC System Analysis and Upgrade	1,439
	<u>Justification</u> : Equipment is ovand codes.	over 30 years old and does not comply with current OSHA standards	
LA	NMCL NORLN	Replace Roof, Bldg. H-100, R8-94	992
	Justification: Repair by replace asbestos contained baseflashin Failure to promptly replace the addition to the potential for fa	Justification: Repair by replacement all the roofing, repair damaged structural decking and abate asbestos contained baseflashing. Roof is 20 years old and has almost surpassed its economic life. Failure to promptly replace the roof could have a negative impact on staff and patient safety in addition to the potential for facility and equipment damage.	
MD	Kimbrough Army Hospital	Window Replacement	770
	Justification: Renovation will	Justification: Renovation will enhance energy conservation of the heating/cooling system.	
MD	Kimbrough Army Hospital	Replace HVAC at Aberdeen Proving Ground	771
	Justification: Equipment is ovand codes.	over 30 years old and does not comply with current OSHA standards	
MD	Kimbrough Army Hospital	Replace Electrical System	835
	Justification: Equipment is ov	over 30 years old and does not comply with current OSHA standards	

and codes.

FY 1996 <u>State</u>	Location/Installation	Project Title	(\$000) <u>Cost</u>
MD	Andrews AFB	Replace HVAC F-Wing	2,200
	Justification: Upgrades 1950	Justification: Upgrades 1950's vintage heating, ventilation, and air conditioning systems.	
МО	Whiteman AFB	Renovate 1st Floor	1,080
	Justification: This project is a conting project will consist of new floor and to giving the entire MTF a "facelift."	a continuation of efforts to renovate each floor of the hospital. The loor and wall coverings, ceilings, and other items that will contribute facelift."	
МО	Whiteman AFB	Upgrade HVAC System	535
	Justification: Project replace adequate climate control and	Justification: Project replaces current HVAC system. Current system can no longer maintain adequate climate control and has exceeded its life expectancy.	
MS	Keesler AFB	Window Replacement	1,000
	Justification: Project replaces all exterior windows wi windows are in disrepair and are non-energy efficient.	Justification: Project replaces all exterior windows with new, energy-efficient units. Current windows are in disrepair and are non-energy efficient.	
MS	Keesler AFB	Follow On From FY95	2,000
	Justification: Continuation c \$500K.	of projects initiated in FY 95. FY95 project effort was less than	

FY 1996 <u>State</u>	Location/Installation	Project Title	(\$000) Cost
NC	NH CLEJ	Repairs Alterations to HVAC System, Bldg. NH-100, RC2-90	576
	Justification: Project provide various AHU's, and rebalance have enough capacity to proheat in winter months. Minc	<u>Justification</u> : Project provides additional chiller, cooling tower, replace various AHU's, modify various AHU's, and rebalance the system in various locations. Present HVAC system does not have enough capacity to provide adequate cooling and air changes. does not provide adequate heat in winter months. Minor construction cost - \$237K.	
NC	Seymour Johnson AFB	Repair Emergency Power System	1,350
	<u>Justification</u> : Project upgrad provides additional emergen	<u>Justification</u> : Project upgrades the current system to meet life safety code requirements and provides additional emergency power expanding technology requirements.	
NC	Pope AFB	Repair/Alter Aeromedical Staging Facility	1,450
	Justification: Required to up	Justification: Required to upgrade existing facility which is in disrepair.	
QZ	Grand Forks AFB	Replace HVAC in MTF	1,100
	<u>Justification</u> : Upgrades 1960's vintage syste mechanical failures interrupting patient care.	<u>Justification</u> : Upgrades 1960's vintage system. Delayed replacement enhances changes of mechanical failures interrupting patient care.	
sc	NH BFT	Upgrade Fire sprinkler System, Bldg. 1, R5-94	1,222
	Justification: Install 3,350 avwill be in compliance with the	automatic fire sprinkler heads and an electric fire pump. The facility the National Fire Protection Association Life Safety Code.	

Real Property Maintenance Activities Major Repair/Major Repair With Concurrent Minor Construction Projects (Costing more than \$500,000.00) Defense Health Program Appropriation FY 1997 Budget Estimates

FY 1996 State	Location/Installation	Project Title	(\$000) Cost
XT	ВАМС	HVAC Modification, Bldg 1029	1,350
	Justification: Current equipr	Justification: Current equipment has deteriorated beyond repair and must be replaced.	
TX	Darnall Army Hospital	Replace Variable Speed HVAC	906
	Justification: Upgrade bring	Justification: Upgrade brings equipment into compliance with current codes and standards.	
TX	Darnall Army Hospital	Replace Chilled Water Distribution System	750
	Justification: Upgrade bring	Justification: Upgrade brings equipment into compliance with current codes and standards.	
XT	NH CORPUS	Repair Air Handlers and Duct Work, Bldg. H-100, R2-92	1,377
	Justification: Repair by replication outside air intake ducts. The from the high salinity of the	Justification: Repair by replacement all air handler units, the pre-heat coils, filter racks, and outside air intake ducts. These repairs are necessary due to major corrosion which has occurred from the high salinity of the ambient air.	
XT	Dyess AFB	Replace Electrical Feeds and Panels	1,110
	Justification: Upgrade, repla aging facility has not kept pa and regulatory requirements.	Justification: Upgrade, replace, and expand the entire electrical power distribution system. The aging facility has not kept pace with increasing power requirements of additional new technology and regulatory requirements.	

FY 1996 <u>State</u>	Location/Installation	Project Title	(\$000) Cost
TX	Brooks AFB	HVAC Epidemiological/Drug Testing	822
	Justification: Construct me reroute/reconfigure all elecieliminates a significant safe accessible only y catwalks.	<u>Justification</u> : Construct mechanical room under building 930. Install new HVAC equipment, reroute/reconfigure all electrical, ductwork, and piping. Project replaces an aged system and eliminates a significant safety problem. Current mechanical room is above ceiling of building and accessible only y catwalks.	
TX	Lackland AFB	Alter Interior, Bldg 1355	009
	Justification: 1951-era building hous in 1993. Interior decor remains subsand warrant immediate replacement.	Justification: 1951-era building houses Substance Abuse Clinic. Exterior received major upgrade in 1993. Interior decor remains substandard. Electrical and mechanical systems are substandard and warrant immediate replacement.	
TX	Lackland AFB	Repair Emergency Power System	1,500
	Justification: Replace threa	Justification: Replace three existing 300 KW generators with three 600 KW units. Replacement	

connected (e.g., main fire pump, medical air compressor, and vacuum pump) to emergency power generator controls. Current generators are at maximum load capacity. Critical systems are not

system as required by life safety code.

includes modification of existing switchgear and conductors, power distribution panels, and

FY 1996 State	I ocation/Installation	Droject Title	(\$000)
anna	LOCALION III SMITH IOII	בות היינו בות היינו	2031
TX	Lackland AFB	Alter Dunn Dental Lab and Supply Storage	200
	Justification: Renovations in expanded prosthetic laborate Pathogen Standards. This valteration will overcome cur	<u>Justification</u> : Renovations in support of a new dental instrument processing center (DIPC) and expanded prosthetic laboratory. The current lack of a central DIPC violates OSHA Blood Borne Pathogen Standards. This violation also jeopardizes the facility's JCAHO accreditation.	
XT	Sheppard AFB	Follow On to FY95 Projects	2,000
	Justification: Continuation of facility enhancements \$500K. Projects for FY96 and FY97 are part of the and corrections that aggregate to more than \$500K.	Justification: Continuation of facility enhancements begun in FY95. FY95 project was less than \$500K. Projects for FY96 and FY97 are part of the five year plan and are for life safety upgrades and corrections that aggregate to more than \$500K.	
UK	Lakenheath AB	Construct Medical Warehouse Addition	991
	Justification: Project addresses significant shortfalls of encompasses separate storage areas for bulk/loose mat space for receiving/breakdown of incoming shipments.	<u>Justification</u> : Project addresses significant shortfalls of space in current warehouse. Addition encompasses separate storage areas for bulk/loose materiel storage, as well as, expanded floor space for receiving/breakdown of incoming shipments.	
UK	Lakenheath AB	Construct/Repair Bldg 914	1,329
	Justification: Required to up	Justification: Required to upgrade existing facility which is in disrepair.	

FY 1996			(2000)
State	Location/Installation	Project Title	Cost
VA	NMCL QUANT	Repair Med Clinic (HVAC) Phase II, Bldg. 2200, RA1-88(1A)	700

Justification: Repair by replacement for existing deteriorated HVAC system which is ineffective, unreliable, and inefficient. Current systems are expensive to operate and maintain. Energy consumption is excessive. Adversely affects mission, morale, safety.

Total Minor Construction: 316	Total Repair and Maintenance: 76,214	Total Active Installations: 76,530	Total Inactive Installations:
Fotal Minor Cons	Fotal Repair and	Fotal Active Insta	Total Inactive Ins

Grand Total: 76,530

FY 1997 State	Location/Installation	Project Title	(\$000) Cost
CA	Edwards AFB	Renovate OB/GYN Area	1,056
	Justification: Project will re providers. Renovation will restrooms.	Justification: Project will renovate vacated administrative area to allow support of OB/GYN providers. Renovation will provide two exam rooms per physician and expanded patient restrooms.	
DC	WRAMC	Repair Roof, Bldg 2	1,000
	Justification: Project remov has reached the end of its use	<u>Justification</u> : Project removes and replaces the center portion and penthouse roofs. Existing roof has reached the end of its useful life and is failing in many areas.	
DC	WRAMC	Repair Courtyard Concrete, Bldg 14	1,200
	Justification: Project replaces 35,C pavers, landscaping, drainage systemetry for soldiers living in Ablevel parking garage, correct acous problems created by poor lighting.	<u>Justification</u> : Project replaces 35,000 SF deteriorating concrete plaza with new concrete precast pavers, landscaping, drainage system, and new lighting in order to create an attractive and useful courtyard for soldiers living in Abrams Hall. Repairs required to correct water leakage into lower level parking garage, correct acoustical echo problems, and to correct security and safety problems created by poor lighting.	

FY 1997 State	Location/Installation	Project Title	(\$000) Cost
DC	WRAMC	Repair/Replace Water Mains, Main Side and Forest Glen	1,000
	Justification: Project replace meters by the DC governmen needed to correct deteriorati waste resulting from leaks, r water supply.	<u>Justification</u> : Project replaces water valves and mains in conjunction with replacement of water meters by the DC government and the Washington Sanitary Sewer Commission. Repairs are needed to correct deteriorating sections of the water network, replace inoperative meters, reduce waste resulting from leaks, reduce shutdowns, and eliminate the potential for contamination of the water supply.	
DC	WRAMC	Replace Overhead Power Lines, 500 Area	912
	<u>Justification</u> : Project replaces detering Repairs are needed to correct saggir interruptions caused by falling lines.	Justification: Project replaces deteriorated wooden poles and cross-arms carrying overhead lines. Repairs are needed to correct sagging lines, reduce maintenance costs, and eliminate power interruptions caused by falling lines.	
FL	Eglin AFB	Construct Mechanical Plant	009
	Justification: Construct shel mechanical plant does not su equipment, e.g., generators,	Justification: Construct shelter to house electrical/mechanical plant equipment. Current mechanical plant does not support electrical or mechanical load of the facility. Replacement equipment, e.g., generators, cannot be house in same area due to space limitations.	
FL	Tyndall AFB	Repair Chill Water Lines	550
	<u>Justification</u> : Repair of orig capability to the facility.	<u>Justification</u> : Repair of original, deteriorated chill water lines to provide adequate coolant capability to the facility.	

FY 1997 <u>State</u>	Location/Installation	Project Title	(\$000) Cost
丑	Tyndall AFB	Renovate Dining Room/Kitchen	1,000
	Justification: Renovate origi patient dining areas.	<u>Justification:</u> Renovate original food service facilities to provide more efficient work spaces and patient dining areas.	
GA	Robins AFB	Hospital Renovation	1,200
	Justification: Project will rer labor/delivery, central supply support increased outpatient is the only means to eliminat	<u>Justification</u> : Project will renovate portions of the main medical facility)inpatient nursing, labor/delivery, central supply, and several administrative/clinical offices). The renovation would support increased outpatient services in effect. As a MILCON project is not feasible, renovation is the only means to eliminate space constraints.	
HI	TAMC	Renovate Fire Sprinkler and Fire Alarm Systems	4,629
	Justification: Upgrades are r	Justification: Upgrades are necessary to comply with NFPA standards.	
HI	TAMC	Repair Water Leaks/Paint Exterior	006
	Justification: Repairs are a r	necessary part of the renewal construction concept.	

FY 1997			(000\$)
<u>State</u>	Location/Installation	Project Title	Cost
IL	NH GLAKES	Mechanical Repairs (Med/Den Clinic), Bldg. 237, R1-92	009
	Justification: Repairs to HVAC, plumbing, el equipment has exceeded its useful life expect building's plumbing and HVAC piping insula unsafe in most areas. the electrical and lighti requirements for safe and healthy operations.	<u>Justification</u> : Repairs to HVAC, plumbing, electrical and lighting systems. The cooling equipment has exceeded its useful life expectancy and is beyond economical repair. The building's plumbing and HVAC piping insulation is either loose, missing or environmentally unsafe in most areas. the electrical and lighting systems will be replaced to meet current requirements for safe and healthy operations.	
IL	NH GLAKES	Interior and Structural Repairs, Bldg. 200-H, R4-92	1,100
	Justification: Project propositive including its pillars, beams, these are showing signs of sare damaged and unable to necessary.	Justification: Project proposes to accomplish repairs to the building's supporting members, including its pillars, beams, floor decks, walls, window wells, exterior bricks and mortar. All these are showing signs of surface cracking and erosion. Repair to walls and window wells which are damaged and unable to hold paint due to moisture penetration. Asbestos removal is also necessary.	
JA	NH OKI	Replace HVAC System (Phase II) Bldg. 6000, R5-93(2)	3,365

affects compliance of room pressurization criteria, indoor air quality, as well as the overall system

performance. For cooling, high room humidities have resulted in dew point condensation with

Justification: Repair by replacement of entire (1950's vintage deteriorating heating, ventilation,

and air conditioning system (HVAC). The HVAC system is presently not air-balanced, which

resulting dampness, mildew and fungus growth, odors, accelerated corrosion and deterioration of

medical equipment.

FY 1997 State	Location/Installation	Project Title	(\$000) Cost
JA	NH OKI	Replace Windows, Bldg. 6000, R2-93	4,791
	Justification: This building is and replaced with sheetmetal typhoons in the region, the eallows humid air to infiltrate wall paint, and delicate equip	<u>Justification</u> : This building is 40 years old. Some of the existing window glass have been broken and replaced with sheetmetal. Due to severe high humidity, salt-laden atmosphere and frequent typhoons in the region, the existing window frames are corroded. Caulking has cracked and allows humid air to infiltrate, severely saturated moisture that damages the acoustical ceilings, wall paint, and delicate equipment. Adversely affects mission, morale, and safety.	
JA	NH YOKO	Replace Absorption Chillers, Bldg. 1401, RC1-95	1,758
	Justification: Repair by repla Existing units have deteriora Chillers require continuous of conditioned. The existing chansatisfactory hospital, bach	<u>Justification</u> : Repair by replacement and upgrade to the two existing absorption chiller units. Existing units have deteriorated due to normal wear and tear during their fifteen years of service. Chillers require continuous operation due to computer usage and area/rooms to be air conditioned. The existing chiller units will expose patients, workers and other personnel to unsatisfactory hospital, bachelor housing and office environment. Minor construction - \$300K	
JA	Kadena AB	Install Sprinkler System	265

<u>Justification</u>: Facility currently not in compliance with requirement for fire suppression system. Project will eliminate noncompliance.

Major Repair/Major Repair With Concurrent Minor Construction Projects (Costing more than \$500,000.00) Defense Health Program Appropriation Real Property Maintenance Activities FY 1997 Budget Estimates

FY 1997			(\$000)
State	Location/Installation	Project Title	Cost
JA	Yokota AB	Life Safety Upgrade Continuation	2,749
	Justification: Follow-on to F	FY96 project to correct deficiencies.	
JA	Yokota AB	Repair Interior	200
	Justification: Upgrade of wa	Justification: Upgrade of wall and floor coverings to enhance appearance for patients and staff.	
JA	Yokota AB	Add/Alter Warehouse	650
	<u>Justification</u> : Requirement to expand current mediinadequate for proper storage of medical materiel.	Justification: Requirement to expand current medical logistics warehouse. Current facility inadequate for proper storage of medical materiel.	
KS	Irwin Army Hospital	Interior Repairs and HVAC Replacement	2,728
	Justification: Building and e current codes and standards.	Justification: Building and equipment has deteriorated to the point that it does not comply with current codes and standards.	
MD	NNMC BETH	Repair Roads, Basewide, Bldg. 810, R24-90	800
	Justification: The existing re provide new pavement to all	Justification: The existing roads require extensive repairs at various locations. Project will provide new pavement to all damaged sections of paved areas.	

FY 1997 State	Location/Installation	Project Title	(\$000) Cost
MD	NNMC BETH	Repairs Parking Lots, Basewide, Bldg. 400, R23-90	009
	Justification: The existing p will correct the damaged sec sections and replacing with	<u>Justification</u> : The existing parking lots require extensive repairs at various locations. This project will correct the damaged sections of paved areas by cutting out and removing the affected sections and replacing with new pavement.	
MD	Andrews AFB	Replace HVAC G/H Wings	1,740
	<u>Justification</u> : Follow-up/continua(Upgrades 1950's vintage systems.	<u>Justification</u> : Follow-up/continuation project to HVAC replacement initiated in FY96 on F-wing. Upgrades 1950's vintage systems.	
МО	General L. Wood Army Hos	General L. Wood Army Hosp Phase II, HVAC Renovation	1,511
	<u>Justification</u> : Deteriorated estandards.	<u>Justification</u> : Deteriorated equipment requires this upgrade to comply with current codes and standards.	
Ŋ	McGuire AFB	Install Signage	610
	Justification: Project includ Hospital. New signage will	Justification: Project includes exterior/interior signage and directories for Walson Community Hospital. New signage will eliminate current hodgepodge and provide uniformity to aid patients.	
Ń	McGuire AFB	Replace Ceilings and Lights	965
	Justification: Installation of second, and third floors of h	<u>Justification</u> : Installation of acoustical ceiling material and energy efficient lighting on first, second, and third floors of hospital. Will improve aesthetics and energy efficiency.	

FY 1997 State	Location/Installation	Project Title	(\$000) Cost
N	McGuire AFB	Replace Doors and Entryways	1,320
	Justification: Project adds ac Electronic doors will replace repair parts.	<u>Justification</u> : Project adds accommodations for handicapped to the facility as required. Electronic doors will replace existing doorways which are difficult to maintain due to a lack of repair parts.	
Ŋ	McGuire AFB	Replace Water and Waste Pipes	1,100
	Justification: Current piping replacement is required.	ig is over 30 years old and is deteriorating rapidly. Immediate	
NJ	McGuire AFB	Renovate Emergency Room	1,500
	Justification: Existing ER is undersize include trauma rooms, treatment room electrical/mechanical support systems.	Justification: Existing ER is undersized and not upgraded since construction in 1960. Project will include trauma rooms, treatment rooms, reception and waiting, new interior finishes, and modern electrical/mechanical support systems.	
Ŋ	McGuire AFB	Replace Induction Coils	1,500
	Justification: Existing coils	Justification: Existing coils original to 1960 construction. All existing coils targeted for	

replacement to eliminate damaged interior finishes due to coil leaks.

FY 1997 <u>State</u>	Location/Installation	Project Title	(\$000) Cost
Ź	McGuire AFB	Misc. Electrical Upgrade	550
	Justification: Additional win	Justification: Additional wiring required to support new energy efficient lighting.	
PR	NH ROOSRD	Repair HVAC System, Bldg. 1790, R1-93	872
	Justification: Repairs to a very deteriorate handlers, and cooling towers are in very prentrifugal chillers are old and inefficient need to be balanced to achieve maximum tanks for steam boilers need replacement.	<u>Justification</u> : Repairs to a very deteriorated and inefficient system. Inducting fan coils, air handlers, and cooling towers are in very poor condition and require replacement. Two 300 ton centrifugal chillers are old and inefficient and must be replaced. air and water distribution system need to be balanced to achieve maximum cooling efficiency. Two deteriorated and rusted fuel tanks for steam boilers need replacement.	
RI	NH NPT	Repair Roads, R1-93	525
	<u>Justification</u> : The current state of repair o degrade until major maintenance is perfor viable maintenance for the problem areas.	<u>Justification</u> : The current state of repair of the roads is rapidly deteriorating and will continue to degrade until major maintenance is performed. Pot hole patching can no longer be considered viable maintenance for the problem areas.	
SC	NH CHASN	Repair/Replace Interior Finish, Bldg. NH-1, R3-90	620

deplorable conditions. These include: wallpaper separating from walls, paint peeling/chipping,

worn carpeting, laminate worn, broken and scared, signage unclear.

Justification: Repairs to bring interior to an acceptable level which are currently deteriorated,

FY 1997 State	Location/Installation	Project Title	(\$000) Cost
SC	NH CHASN	Repair Exterior Windows, Bldg. NH-1, R4-89	1,467
	Justification: Repairs requir allows water penetration. A precast concrete panels. Ad	Justification: Repairs required to stop deterioration to window wall joints were cracked and allows water penetration. Also, water penetration and mildew evident within mortar, bricks, and precast concrete panels. Adversely affects safety, morale.	
XT	Lackland AFB	Alter Interior, Bldg 1354	009
	Justification: 1951-era build received major upgrade in 1 systems are substandard and	Justification: 1951-era building houses Life Skills and Adolescence Psychology Clinics. Exterior received major upgrade in 1993. Interior decor remains substandard. Electrical and mechanical systems are substandard and warrant immediate replacement.	
TX	Lackland AFB	Replace 13 KV Switchgear	1,600
	Justification: Recommende Range Plan. This plan ident Hall Medical Center through equipment life expectancy.	<u>Justification</u> : Recommended upgrade as part of the 1990 AETC/DEMU Total Energy Long Range Plan. This plan identifies the requirements for meeting the utility requirements of Wilford Hall Medical Center through the year 2007. Current system is nearing end of recommended equipment life expectancy. Failure to replace could result in a catastrophic equipment loss.	
TX	Lackland AFB	Clean, Repair, Seal Exterior to WHMC	2,000
	Justification: Severe weath	Justification: Severe weathering has affected integrity of concrete areas. Concrete has given way	

to expose reinforcement bars. Exterior detracts from appearance of Air Force's largest medical

FY 1997	I contion Anatollation	Drainet Title	(\$000)
State		THE THE	1000
TX	Sheppard AFB	Follow On to FY95 Project	2,000
	Justification: Continuation of facility enhancements \$500K. Projects for FY96 and FY97 are part of the and corrections that aggregate to more than \$500K.	of facility enhancements begun in FY95. FY95 project was less than and FY97 are part of the five year plan and are for life safety upgrades ate to more than \$500K.	
VA	NMCL QUANT	Renovations to Medical Clinic, Bldg. 2200, RC2-92	1,005
	Justification: Repairs/altera renovation to public restroo of ambulatory clinic waiting	<u>Justification</u> : Repairs/alterations include upgrade to electrical system, repairs to foundation, renovation to public restrooms, replace access roofs, renovation to clinical areas, and expansion of ambulatory clinic waiting room. Adversely affects patient care effectiveness. Minor - \$160K.	
VA	NMCL QUANT	Resurface Roads and Repair/Replace Curbs/Sidewalks, Bldg. 011, R7-92	800
	Justification: Repairs are not showing reflective cracks in the curbing is no longer effe	<u>Justification</u> : Repairs are necessary to the roads surfaced with bituminous concrete which is showing reflective cracks in two directions. There is a build up of the pavement to the point that the curbing is no longer effective. Also, replacement of sidewalk section needed.	
WA	MAMC	CTMC Remediation	1,075

Justification: Repairs and alterations required to renovate facility for use as a consolidated TMC.

Major Repair/Major Repair With Concurrent Minor Construction Projects Defense Health Program Appropriation Real Property Maintenance Activities (Costing more than \$500,000.00) FY 1997 Budget Estimates

Location/Installation FY 1997 State

Project Title

(\$000) Cost

57,393 58,073 989 Total Repair and Maintenance: Total Inactive Installations: Total Minor Construction: Total Active Installations:

Grand Total:

58,073